iPod Nano 6 Display Breakout - Bug #601


TLV61220 footprint wrong

03/18/2015 06:28 PM - Andrew Kohlsmith

Status:	Feedback	**Start date:**	03/18/2015
Priority:	Normal	**Due date:**	
Assignee:	Andrew Kohlsmith	**% Done:**	80%
Category:		**Estimated time:**	0:00 hour
Target version:			

Description

The SOT23-6 footprint I created is mirrored top-to-bottom (i.e. pin 1 is pin 3, pin 4 is pin 6).



The layout'll have to be fixed. I've updated the library but I wonder what other SOT23-6 parts I have that are wrong.

For now the fix for this board is to take the pins and bend them backward and mount the part upside down.

History

#1 - 03/18/2015 06:38 PM - Andrew Kohlsmith

- File picture963-1.png added

- Description updated

#2 - 03/18/2015 08:19 PM - Andrew Kohlsmith

Part doesn't work for us anyway, see #602

#3 - 03/18/2015 08:46 PM - Andrew Kohlsmith

Footprint fixed in commit:122c7eb.

#4 - 03/18/2015 08:47 PM - Andrew Kohlsmith

- Status changed from New to Feedback

- % Done changed from 0 to 80

Files

picture963-1.png	7.46 KB	03/18/2015	Andrew Kohlsmith