iPod Nano 6 Display Breakout - Bug #469

RST#, BL lines should have pulldown as appropriate

03/01/2014 03:07 PM - Andrew Kohlsmith

Status:	Feedback	**Start date:**	03/01/2014
Priority:	Normal	**Due date:**	
Assignee:	Andrew Kohlsmith	**% Done:**	80%
Category:		**Estimated time:**	0:00 hour
Target version:			

Description

Just from a "nice to have" perspective, RST# and BL are the only two signals that don't have a defined state when not being driven. They should both be pulled low so that the board's native state is to have a dark, in-reset LCD. This would give the cleanest power-up.

History

#1 - 03/01/2014 10:07 PM - Andrew Kohlsmith

- Status changed from New to Feedback

- % Done changed from 0 to 80

Applied in changeset nanov6|commit:dd7a3538aadc34740b98c8baf410204573016 95f.