iPod Nano 6 Display Breakout - Bug #471

3.3VEN signal is active low... make it active high

03/01/2014 03:16 PM - Andrew Kohlsmith

Status:	Feedback	**Start date:**	03/01/2014
Priority:	Normal	**Due date:**	
Assignee:	Andrew Kohlsmith	**% Done:**	80%
Category:		**Estimated time:**	0:00 hour
Target version:			

Description

I just noticed that the 3.3VEN signal is active-low. I don't recall why I would have done such a thing. It should be active-high like all of the other signals, which means the FET should be an n-channel BSS84 and the pullup should be a pull-down.

History

#1 - 03/01/2014 10:07 PM - Andrew Kohlsmith

- Status changed from New to Feedback

- % Done changed from 0 to 80

Applied in changeset nanov6|commit:c32c1ad91d43bd54e9a9f71ce357a46d15634e97.

#2 - 03/18/2015 09:24 PM - Andrew Kohlsmith

Fixed for real in commit:a166d76.