iPhone 4 HSMC Interface - Bug #571

R7/C4 designators are switched

08/28/2014 02:03 PM - Andrew Kohlsmith

Status:	New	**Start date:**	08/28/2014
Priority:	Normal	**Due date:**	
Assignee:	Andrew Kohlsmith	**% Done:**	0%
Category:		**Estimated time:**	0:00 hour
Target version:			

Description

On the board silkscreen the R7 and C4 designators need to be swapped. The ordering suggests that the parts are in R7 C4 order when in fact they are C4 R7 order.