Model Rocket Logger/Locator - Bug #588

VBATT doesn't go to an analog input

01/21/2015 09:06 AM - Andrew Kohlsmith

Status:	New	**Start date:**	01/21/2015
Priority:	Normal	**Due date:**	
Assignee:	Andrew Kohlsmith	**% Done:**	0%
Category:		**Estimated time:**	0:00 hour
Target version:			

Description

I'd assumed that any pin could be routed to the ADC; only P0.1 through P0.6 and P0.26/P0.27 are connected to the ADC.

Currently VBATT is routed to P0.9 on pin 15. I'm breaking that connection and wiring it to P0.5 on pin 9 which is unused.

History

#1 - 01/21/2015 09:33 AM - Andrew Kohlsmith

- Description updated