iPod Nano 6 Display Breakout - Task #603

Bug # 602 (New): boost converter won't boost high enough

use an LED driver for the backlight

03/18/2015 08:21 PM - Andrew Kohlsmith

Status:	New	**Start date:**	03/18/2015
Priority:	Normal	**Due date:**	
Assignee:	Andrew Kohlsmith	**% Done:**	0%
Category:		**Estimated time:**	0:00 hour
Target version:			

Description

Need to bring the LED- line out so it can connect to the feedback path. See #602.