iPod Nano 6 Display Breakout - Task #604

Remove the data/clk pulldowns

03/18/2015 08:23 PM - Andrew Kohlsmith

Status:	Feedback	**Start date:**	03/18/2015
Priority:	Normal	**Due date:**	
Assignee:	Andrew Kohlsmith	**% Done:**	80%
Category:		**Estimated time:**	0:00 hour
Target version:			

Description

I need finer control over the DP/DM and CLKP/CLKM lines in order to properly transition between the LP and HS modes. I misunderstood the function of these signals.

The board works fine with them populated, but they're useless.

History

#1 - 03/18/2015 08:46 PM - Andrew Kohlsmith

- Status changed from New to Feedback

- % Done changed from 0 to 80

Removed in commit:122c7eb.